ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0401	NA	18TH A CROSS
Segment No.	**Total Length (m)**	
14/S-W0401/S072513	189.56	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	189.56	77.505062	13.056579	77.505484	13.058241	W0079	W0086

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS TO ROADS AND DRAIN AT 18TH A CROSS	5000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender	ROAD AND WORK	014-18-000033
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/30/17-18	18/12/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
18/12/2017	17/03/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
L RAGHUNANDAN		0.00
Phone No.	**E-Mail ID**	
9743188999		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Manjunath
Date of Inspection	**Remarks**	
12/01/2018		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	VIJAY KUMAR	12/01/2018	11/02/2018	COMPLETED
EE	SHESHADRI	12/01/2018	11/02/2018	COMPLETED
AEE	SHIV KUMAR ODEYAR	12/01/2018	11/02/2018	COMPLETED
AE	MANJUNATH	12/01/2018	11/02/2018	COMPLETED
AE	MANJUNATH	12/01/2018	11/02/2018	COMPLETED